ASSEMBLY INSTRUCTIONS

DEAR CUSTOMER,

Caution:

1. Please read all instructions before assembly and check the carton for any parts that may have come loose during shipment. It is recommended to use two or more persons during the assembly process.
2. Please do not discard any packaging before you have checked all the parts and fittings are included. If for any reason this product needs to be returned it must be returned packed in its original packaging.
3. Assemble this product on a flat and clean surface to avoid scratching.



ASSEMBLY INSTRUCTIONS

PARTS LIST



HARDWARE LIST

LABEL	PICTURE	DESCRIPTION	QTY	LABEL	PICTURE	DESCRIPTION	QTY
A		Bolt M8 x 20 mm	34	D		Screw 5 x 70 mm	2
B		Bolt M8 x 45 mm	13	E		Check Nut	6
C		Bolt M8 x 75 mm	2	F		Angle iron	4
				G		Bolt M8 x 55 mm	1

TOOL LIST

LABEL	PICTURE	DESCRIPTION	QTY
T-1		Allen key 5#	1
T-2		Screwdriver (not provided)	
T-3		Spanner	1

ASSEMBLY INSTRUCTIONS

Step 1:



B x 8 Bolt M8 X 45 mm	C x 2 Bolt M8 X 75 mm
D x 2 Screw 5 x 70 mm	T-1 x 1 Allen Key 5#
T-2 x 1 Screwdriver (not provided)	

Step 2:



A x 4 Bolt M8 X 20 mm	T-1 x 1 Allen Key 5#

ASSEMBLY INSTRUCTIONS

Step 3:



A x 8 Bolt M8 X 20 mm	F x 4 Angle iron
T-1 x 1 Allen Key 5#	

Step 4:



A x 8 Bolt M8 X 20 mm	T-1 x 1 Allen Key 5#

ASSEMBLY INSTRUCTIONS

Step 5:



A x 8 Bolt M8 X 20 mm	T-1 x 1 Allen Key 5#

Step 6:



B x 4 Bolt M8 X 45 mm	E x 4 NUT
T-1 x 1 Allen Key 4#	T-3 x 1 Spanner

ASSEMBLY INSTRUCTIONS

Step 7:



A x 4 Bolt M8 X 20 mm	T-1 x 1 Allen Key 5#

Step 8:



B x 1 Bolt M8 X 45 mm	E x 2 Check Nut
G x 1 Bolt M8 X 55 mm	T-1 x 1 Allen Key 5#
	T-3 x 1 Check Nut

ASSEMBLY INSTRUCTIONS

Step 9:



A x 2 Bolt M8 X 20 mm	T-1 x 1 Allen Key 5#

Step 10: