



## Hardware




## Tools Required


We spower tools can strip threads if over tightened.



(not included)




(not included)




## Components


Make sure there is no shortage or defect of the included parts and/or screws. If you find a shortage or defect, please contact the customer service for replacement.




**S**  
1x



**T**  
1x




**U**  
1x




**V**  
1x

## Components


If you cannot find the parts you need of this product, please inform the customer service of your retailer.




**W**  
1x




**X**  
1x




**Y**  
1x




**Z**  
1x




**A1**  
3x



**B1**  
3x




**C1**  
3x




**D1**  
3x




**F1**  
3x



**G1**  
3x




**H1**  
1x






**I1**  
1x

# Assembly Instructions

1.




2.




# Assembly Instructions


5.




6.





7.



8.




# Assembly Instructions




Assembly Instructions


13.




14.



15.




16.



Assembly Instructions

17.



18.

