

Assembly Instruction


HARDWARE

PART#	DESCRIPTION	DRAWING	Q'TY
A	Bolt(ϕ 1/4"*2"L)		2
B	Bolt(ϕ 1/4"*2-1/2"L)		4
C	Spring washer(ϕ 1/4"* ϕ 1/2")		6
D	NUT		6


LIST

PART#	DESCRIPTION	DRAWING	Q'TY
E	Wood Dowel ϕ 8*30mm		4
F	Wrench (4mm)		1
G	Wood screw(8#*1-1/2"L)		4
H	Cover		6


STEP 1




STEP 2



STEP 3



STEP 4



MADE IN CHINA

Assembly Instruction


HARDWARE

PART#	DESCRIPTION	DRAWING	Q'TY
A	Bolt(ϕ 1/4"*2"L)		2
B	Bolt(ϕ 1/4"*2-1/2"L)		4
C	Spring washer(ϕ 1/4"* ϕ 1/2")		6
D	NUT		6


LIST

PART#	DESCRIPTION	DRAWING	Q'TY
E	Wood Dowel ϕ 8*30mm		4
F	Wrench (4mm)		1
G	Wood screw(8#*1-1/2"L)		4
H	Cover		6


STEP 1




STEP 2



STEP 3



STEP 4



MADE IN CHINA

Assembly Instruction


HARDWARE

PART#	DESCRIPTION	DRAWING	Q'TY
A	Bolt(ϕ 1/4"*2"L)		2
B	Bolt(ϕ 1/4"*2-1/2"L)		4
C	Spring washer(ϕ 1/4"* ϕ 1/2")		6
D	NUT		6


LIST

PART#	DESCRIPTION	DRAWING	Q'TY
E	Wood Dowel ϕ 8*30mm		4
F	Wrench (4mm)		1
G	Wood screw(8#*1-1/2"L)		4
H	Cover		6


STEP 1




STEP 2



STEP 3



STEP 4




MADE IN CHINA


Assembly Instruction

HARDWARE				LIST			
PART#	DESCRIPTION	DRAWING	Q`TY	PART#	DESCRIPTION	DRAWING	Q`TY
A	Bolt(ϕ 5/16"*2"L)		8	C	Flat washer (ϕ 5/16"* ϕ 3/4")		8
B	Spring washer(ϕ 5/16"* ϕ 1/2")		8	D	Wrench (5mm)		1

STEP 1



STEP 2



MADE IN CHINA