




HARDWARE


A	x16	B	x16	C	x28	D	x28	E	x6	F	x2	G	x12
							4x40mm						3x12mm
H	x4	I	x2	J	x8	K	x8	L	x14	M	x2	N	x2
	4x11mm		4x8mm						3x14mm				
O	x2	P	x4	Q	x2	R	x1	S	x8	T	x4	U	x16
	3x14mm				4x30mm		4mm		6x55mm				4x25mm
V	x2	W	x2										
	6x50mm		10x10mm										





1



2





3




G	X6	P	X2
3x12mm			


4




5



6




7




U	X4
4x25mm	

8




U	X4
4x25mm	

9




D	X6
4x40mm	

10




D	X8
4x40mm	


11





13





12






16



M	X2	Q	X2
			
		4x30mm	


17



x2

A	X4	C	X4	D	X8	B	X4	L	X8
									
				4x40mm				3x14mm	


18




x2

F	X2	I	X2
			
		4x8mm	


20



19



Screw from the inside of the drawers



H	X4
	
4x11mm	