









HARDWARE

A	x18	B	x16	C	x30	D	x8	E	x4	F	x2	G	x2
							4x40mm				4x30mm		4x14mm
H	x2	I	x2	J	x4	K	x2	L	x6	M	x2	N	x4
					3.5x12mm				3x12mm		4x11mm		
O	x10	P	x2	Q	x1	R	x1						
					4x20mm								





1



A X4





2



C X16




3




K	X2	L	X6
		3x12mm	


4



C X8



5









A x12

C X4 A X12




6



B X12




7




E	X2	D	X2
			
4x40mm			

8




E	X2	D	X2
			
4x40mm			

9




B	X4
	

10



rear panels	
O	X10
	


11



N X4



13




Q X1 R X1




4x20mm



12



C X2 J X4 A X2 P X2 D X4




3x14mm




4x40mm

14




I	X2	G	X2
		4x14mm	

15







Pre-drilled hole at wall



H	X2	F	X2
		M4x30mm	

16



Screw from the inside of the drawers

M	X2
	4x11mm