



DRESSING TABLE ASSEMBLY INSTRUCTIONS



PARTS LIST




- | | |
|-------------------|---------|
| 1. MIRROR | X 1 PC |
| 2. WOODEN SUPPORT | X 2 PCS |
| 3. TABLE BACK | X 1 PC |
| 4. DESKTOP | X 1 PC |
| 5. TABLE LEG | X 4 PCS |
| 6. CUSHION | X 1 PC |
| 7. STOOL FRAME | X 1 PC |
| 8. STOOL LEG | X 4PCS |

HARDWARE LIST


- | | | | | | |
|---|---|----------------|---|---|----------------|
| A |  | M6X50MM X8 PCS | B |  | M6X40MM X8 PCS |
| C |  | M4X50MM X2 PCS | D |  | M4X40MM X3 PCS |
| E |  | M4X25MM X4 PCS | F |  | M4X20MM X4 PCS |
| G |  | X1 PC | | | |

STEP 1




A X 8PCS

STEP 2




D X 3PCS
E X 4PCS

STEP 3




C X 2PCS

STEP 4



B X 8PCS

STEP 5



F X 4PCS

STEP 6

